Oil Field Environmental Incident Summary

Responsible Party: ONEOK Rockies Midstream **Well Operator:** ONEOK ROCKIES MIDSTREAM

Well Name: Crosby Compressor Station

Field Name: Well File #:

Date Incident: 3/28/2015 Time Incident: 14:00 Facility ID Number:

County: DIVIDE Twp: 162 Rng: 98 Sec: 11 Qtr: NE

Location Description: Crosby Compressor Station

10045121ST Ave NW

Crosby, ND

Submitted By: Kim Rudningen Received By:

Contact Person: Kim Rudningen

2700 Lincoln Ave SE Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 24 Gallons 24 Gallons

Description of Other Released Contaminant:

Natural gas condensates

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

There are no immediate risks associated with this release.

Areal Extent:

The incident was contained to the ground surface immediately below the unit.

Potential Environmental Impacts:

There are no other environmental impacts associated with this release.

Action Taken or Planned:

A vacuum truck that was on site was immediately dispatched to the location and all of the liquids were sucked up and removed from the site for disposal. No further remediation will be required.

Wastes Disposal Location: Recovered wastes were removed to a certified disposal location.

Agencies Involved:

Updates

Date: 3/30/2015 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a release of 24 gallons of natural gas condensate was contained below the unit on the well facility site. Compressor stations require further followup even when contained on facility.

Date: 5/29/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 13:30 5/28/2015.

No apparent sign of significant spill at location. No photos taken.

No followup is necessary.